






Puffer
Buffer

Fehlbed.-Schliessstueck MVS
Misshandl. striker MVS



Ausfuerung RC2 +MVS / RC2 + MVS design

IMO_403

[illegible]